



**NUS**  
CORPORATION

19 CROSBY DRIVE  
BEDFORD, MASSACHUSETTS 01730  
617-275-2970



SDMS DocID

564993

Superfund Records Center

SITE: Pontiac Enterprises

BREAK: 1.18

OTHER: 564993

June 11, 1990

C-583-6-0-52

Mr. Sean O. Coffey, Esquire  
Licht and Seminoff  
1 Park Row  
Providence, Rhode Island 02903

Subject: Proposed Site Reconnaissance Activities  
Pontiac Enterprises LTD  
Warwick, Rhode Island  
TDD No. F1-8901-15  
Reference No. \$375RI73IS  
CERCLIS No. RID069857514

Dear Mr. Coffey:

NUS Corporation is under contract to the U.S. Environmental Protection Agency (U.S. EPA) Region 1, as a technical and management services contractor in support of the EPA's hazardous waste site assessment activities. In this capacity, the NUS Field Investigation Team (NUS/FIT) is conducting a Screening Site Inspection (SSI) of Pontiac Enterprises LTD, located at 334 Knight Street in Warwick, Rhode Island. As part of the SSI activities, a Site Reconnaissance will be performed.

Per your request as a condition for site access I am sending you a description of the reconnaissance activities proposed for the Pontiac Enterprises LTD site. The NUS/FIT activities are as follows.

The onsite reconnaissance will be performed to observe characteristics of the site and the surrounding area. Activities will include a facility walkover, the taking of photographs documenting the existing site environment, the completion of a site sketch, and the completion of the activities noted in the attached Site Reconnaissance Checklist. Prior to beginning reconnaissance activities, NUS/FIT personnel will establish a

command post and decontamination area. The location of these areas will be dependent upon site conditions. NUS/FIT will not enter any onsite structures as part of this reconnaissance.


If you have any questions or concerns, please contact me at (617) 275-2970. Thank you very much for your assistance.

Sincerely,

*Alla Milikovsky*

Alla Milikovsky  
Project Manager

Approval:

  
Robert Jubach

cc: J. Weiss  
D. Smith/EPA  
S. Hayes/EPA

**ATTACHMENT**

**Site Reconnaissance Checklist  
Pontiac Enterprises LTD**

## SITE RECONNAISSANCE CHECKLIST

- \* Monitor and record ambient air quality.
- \* Record facility site sketch and location of any disposal areas.
- \* Document onsite features, including number of buildings, equipment.
- \* Determine distance to the nearest residence(s) or businesses from the site.
- \* Determine onsite surface water drainage pattern, distance to the nearest surface water body.
- \* Identify areas of stained soil and/or stressed vegetation.
- \* Determine the accessibility to the property.
- \* Note leachate outbreaks, exposed waste.
- \* Identify any potential onsite source areas (e. g. lagoon) of contamination, note size and containment.
- \* Note quantity/contents of any containers onsite.
- \* Verify site location on USGS topo map.